



// ENSURE SAFETY



Phone: +49 2272 9060 0
Mail: info@nitrassafety.com
Web: www.nitrassafety.com



EN ISO 21420:2020 **Schutzhandschuhe – Allgemeine Anforderungen und Prüfverfahren**

Storage / use / servicing: Store in a cool, dry place. Keep away from direct sunlight, UV rays or ozone sources.

Do not store in buckled condition or under weight load. If possible, store or transport the product in its original packaging. Influences such as light, humidity, temperature and natural changes in materials over a longer period of time can lead to changes in product properties. Exact information on storage time and service life of the PPE is not possible, since both parameters depend on the respective type of storage, temperature, humidity, degree of wear and intensity of use, among other things. Check this product for damage or material changes (e.g. brittle, cracked coatings / materials, holes, colour changes etc.) after prolonged storage and before and after each use. Before each use, check this product for suitability for the intended activity and for the correct size. Unsuitable or defective products must be disposed of and never used. The size of the product may differ from the specifications, e.g. due to stretching.

All performances were determined by tests under laboratory conditions. It is therefore recommended to check whether the PPE is suitable for the intended use, as the conditions at the workplace can differ from those of the type examination depending on various parameters (e.g. temperature, abrasion, intensity of use). If PPE has already been used, it can offer lower performance due to the degree of wear. The manufacturer accepts no responsibility for any improper use of the product.

Instructions for wearing the product: Make sure your hands are clean and dry before putting on gloves. Insert your fingers into the respective glove and pull the glove loosely over your hand on the knitted wrist or cuff. Make sure that the fit is correct. Gloves should have a tight and snug fit on the palm of the hand, fingers and gaps between them. Fingernails, jewellery, excessive stretching and pulling can damage the gloves. A glove should be taken off after use in such a way that the outside of the gloves does not come into contact with clothing or skin, as the gloves can be visibly and invisibly contaminated with harmful substances. Accordingly the inside must come outwards. First remove the fingertips of the glove from your fingers. The knitted wrist or cuff can then be rolled outwards in order to remove the glove. To ensure that the glove retains its comfort, it should be cleaned after each use in accordance with the cleaning and maintenance instructions. If necessary, this can and should be done while wearing the gloves.

A suitable skin protection product can be used before starting work (after breaks and if necessary after

EN ISO 31439:2020 *Cuentas de patrimonio. Requisitos generales e métodos de prueba*

Se c'è il rischio di incastrarsi nelle parti in movimento della macchina, non indossare i guanti.

Le marquage CE atteste que le produit répond aux exigences fondamentales en matière de protection de la santé et de sécurité du Règlement (UE) 2016/425. La déclaration de conformité CE peut être consultée à ce.doc.nitrax-safety.com.

Ce produit est un équipement de protection individuelle de la catégorie de risque II. Il vous protège contre les risques suivants: Risques mécaniques. Tous les domaines d'application autres que ceux susmentionnés sont expressément exclus. Ce produit n'offre donc aucune protection notamment contre les risques suivants: Produits chimiques, Micro-organismes, Froid, Risques thermiques (chaleur et/ou feu), Chocs électriques, Rayonnement, Travaux au je t'aute pression. Merci de respecter les pictogrammes et consignes apposés, et les niveaux de performance associées.

Entreposage/utilisation/condition: Stocker au frais et au sec. Tenir éloigné de la lumière du jour directe, du rayonnement ultraviolet ou des sources d'ozon. Ne pas entreposer à l'état plié ou sous une forte charge.

[illegible]

0 Minste ytelsestrinn
X Ikke testet eller kan ikke brukes på grunn av materialet eller utformingen
Alle tester ble utført iht. laboratoriebetingelser på innsiden av hånden, og ved hjelp av disse ble de aktuelle ytelsestrinnene registrert.

EN ISO 21420:2020Beskyttelseshansker – Generelle krav og testprosedyre			
Testparametere		Ytelsestrinn	Testresultat
Fingerferdighet		1-5	5

Hvis det foreligger fare for å henge seg fast i bevegelige maskindeler, skal det ikke brukes hansker.

EN 388:2016+A1:2018		Beskyttelseshansker mot mekaniske farer		
EN 388	Testparametere	Ytelsestrinn	Testresultat	
	A	Slitefasthet	1-4	2
	B	Snittstyrke (Coupe-test)	1-5	1
	C	Rivestyrke	1-4	1
	D	Stikkstyrke	1-4	1
	E	Snittstyrke (TDM)	A-F	X
ABCDE				

Hvis hansker består av to eller flere lag, gjengir ikke totalklassifiseringen nødvendigvis yteevenen til de ytterste lagene.
Testresultatet for snittstyrke (B) er bare en henvisning. TDM-snittstyrketesten (E) gir referanseresultater når det gjelder ytelse.



Produsent



Produksjonsår og-måned



Resirkuleringssymbol (kun for FR)



Les veiledninger og informasjon fra produsenten



CE-merking



EAC-merking



UkrSePro-merking